Make Your City Smart



Existing Situation Report
Vir Bhagat Singh Garden,
Surat

Surat Smart City Limited
Surat, Gujarat
September, 2016

Table of Contents

1.	Introduction	3
2.	Facts about the Park	3
3.	Annexure 1: Map of Existing Feature	6
4.	Annexure 2: Picture Gallery of Existing Features	7

VIR BHAGAT SINGH GARDEN, SURAT

1. INTRODUCTION

Vir Bhagat Singh Garden is located on Tikam Nagar Road, it lies in East zone, Umar Wada Mata Wadi ward. The Area of the park is 6400 sqm. The park has two entry and exits points. It is a Neighbourhood Park and caters to around 1.5 Lakhs persons. It is active park as several activities can been seen happening in the park.

The park has huge Kids play set area and as well as exercising machines for adults.

2. FACTS ABOUT THE STREET

Some of the salient notable facts in this street is given in table mentioned below:

Features	Status as on Date
Category of Park	Neighborhood Park
Total Area(in.sq.m)	6400 sq.mtrs
Neighboring Streets	Tikam Nagar Road
Catchment Population of the Park	The catchment population of park is
	around 1.5 lacs
General Condition	The park is Flat and with fair level of
_	cleanliness (ref. photo no. 4, 9, 11, 12)
Open Green Space Landscaped Area	The condition of the open Green space is
	quite fair, clean and almost flat.
	(ref. photo no. 7, 11, 12)
Flower Variety	There are few variety of flowers, but no
	markers are provided. (ref. photo no 2, 8)
Shrubs & Bushes	There are few shrubs and bushes with
	colours.
Wooded Area	There is a flat wooded area in the park
	.Although the wooded area is not dense.
Poved Pothwaya	The pathway provided is in good
Paved Pathways	The pathway provided is in good condition around 6 Mtrs and 3 mtrs (the
	internal pathway) Few benches are
	provided along the pathway and is free
	from obstructions
Motor Avec	Not available
Water Areas	
Eating Features	There is an eating Kiosk outside the
Driving Fratures	park.
Drinking Features	There is only one drinking feature.
Facilities	Boundary wall: The boundary wall is
	hybrid type having brick wall and grill
	over it. (ref. photo no. 17, 24, 19)
	Entry Gate: The park has 2 metallic
	gates. (ref. photo no. 15,1)
	Recreational Centre: No availability of
	Recreational Centre
	Illumination In Park: The park High


	mass lights (rof photo no 19 12)
	mass lights. (ref. photo no 18, 13)
	Public Convenience: There is one washroom.
	Parking: There is no designated parking
	space. The car are parked outside the
	park along the road
	Dustbins: There is a provision of
	dustbins; the number of dustbins is 6 (ref.
	photo no. 6, 23)
	Signboards: Few signboards are
	provided at certain location
	provided at cortain location
	Rain water Harvesting: There is a
	provision for rain water harvesting.
	(ref. photo no. 16)
	(101. prioto 110. 10)
Sitting or Resting Features	Benches: The park has 70 cement
Onting of Nesting Features	concrete benches and are in good
	condition. (ref. photo no. 7, 4, 12)
	Condition. (<i>rer. prioto no. 1, 4, 12)</i>
	Table: There are no evallability of Dienia
	Table: There are no availability of Picnic
	Table
DI 0 1/01	Shelter/ Hut: There is availability of hut
Play Set/ Structure	There is availability of play sets
	No of structures:
	Slide down structures 6
	Hanging structures : 4
	Things to climb on, up or through: 4
	Swinging structures : 6
	Spring toys : 0
	The soil is loose. There is ample of
	Openness. There is availability of seating
	structures and has 33% shaded area
	with fair condition. The play area has
	proper lighting.
	Slide down structures:
	The structure has 4 straight slides
	1 Curve slide
	1 Tube slides
	Poles
	Pole slides
	Height of ground to top of sliding surface
	less than 5 ft
	Hanging structures

	2 movable rings are present, made out of metal and height off ground is 4 ft
	Things to climb on, up or through
	Swinging structures: There are 6 swinging structures, with average height of less than 2 feet.
	Spring toys: The is no availability of animal spring toys
Play Area	There is small play area for kids (ref. photo no. 20)
Features for differently abled	No provision for differently abled

Annexure 1: Map of Existing Features



Annexure 2: Picture Gallery of Existing Condition





01-MAIN ENTRANCE TO PARK.jpg



03-CONDITION OF WALKWAY.jpg



05-PLANTERS.jpg



17-CONDITION OF BENCH AND DRAIN.jpg



02-EXISTING CARE TAKER ROOM.jpg



04-SITTING AREA IN PARK.jpg



06-CONDITION OF DUSTBINS.jpg



08-SHADED WALKWAY.jpg



09-EXISTING CONDITION.jpg



11-OBSTRUCTED WALKWAY.jpg



13-CONDITION OF EXISTING FLOOD LIGHT.jpg



15-SECONDARY ENTRANCE GATE OF PARK.jpg 16-EXISTING RAIN WATER HARVESTING CONDITION.jpg



10-CONDITION OF BOUNDARY WALL.jpg



12-CONDITION OF BENCH AND EXERCISE EQUIPMENTS.jpg



14-SHADED WALKWAYS.jpg





17-PARKING AT SECONDARY ENTRANCE GATE.jpg



18-ELECTRIC LIGHT POLE.jpg



19-CONDITION OF DRINKING WATER FACILITY.jpg



20-PLAY AREA.jpg



21-SHADED WALKWAY.jpg



22-UNIQUE TREE.jpg



23-ACCESS TO PLAY AREA.jpg



24-ENCROACHED FOOTPATH AT MAIN ENTRANCE.jpg